



Technical Service Bulletin

Technical Service Bulletin: TSB220160

Released Date: 25-Oct-2022

New Variable Geometry Turbocharger (VGT) Actuator Sealing Gaskets: Fault Codes 1894, 1897, 2636, 2634, 2387, 6432, or 2449.

New Variable Geometry Turbocharger (VGT) Actuator Sealing Gaskets: Fault Codes 1894, 1897, 2636, 2634, 2387, 6432, or 2449.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- B6.7 CM2350 B121B
- B6.7 CM2350 B135B
- B6.7 CM2350 B136C
- B6.7 CM2350 B148B Stop-Start Applications
- B6.7 CM2350 B157C
- B6.7 CM2450 B155B
- ISB6.7 CM2350 B101
- ISB6.7 CM2350 B103
- ISB6.7 CM2350 B142
- ISL9 CM2350 L101
- ISL9 CM2350 L111
- L9 CM2350 L116B
- L9 CM2350 L119B
- L9 CM2350 L120C
- L9 CM2350 L123B
- L9 CM2350 L129C
- L9 CM2350 L133C
- L9 CM2450 L126B
- QSB6.7 CM2350 B105
- QSB6.7 CM2350 B112
- QSB6.7 CM2350 B130
- QSB6.7 CM2350 B145
- X12 CM2350 X119B
- X12 CM2450 X137B

- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2450 X124B
- X15 CM2450 X134B

Description of Change

New turbocharger actuator mounting kits containing new sealing gaskets available to service a new turbocharger actuator part number.

Service Instructions

- If a new VGT actuator is required, the new VGT actuator will come with sealing gaskets installed.
- If a turbocharger is required, the new turbocharger kit will come with multiple sets of VGT actuator sealing gaskets.
- Choose the sealing gaskets from the mounting kit that match the sealing gaskets removed from the VGT actuator.

Service Parts

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts				
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
KIT, MOUNTING	5550398	No	No	6378654

Part Identification

- Use the descriptions and images below to choose the correct sealing gasket from the turbocharger mounting kit.
- Existing VGT actuators have a flat pinion gear cavity and ribs in pairs on the sealing gasket - one on ID, one on OD.
- The new VGT actuator has a chamfer on the pinion gear and a contoured pinion gear cavity.
- The sealing gaskets for the new VGT actuator have ribs grouped in threes - two on inner diameter, one on the outer diameter.



Figure 1, Left: Existing Design. Right: New Design



Figure 2, Left: Existing Design. Right: New Design.

Document History

Date	Details
2022-8-1	Module Created

Last Modified: 25-Oct-2022
