

Fault Code: 1412

Droop Adjust Potentiometer Circuit

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 1412 PID(P): SPN: FMI: Lamp: Warning SRT:	Droop adjust potentiometer signal is shorted high.	The droop adjustment feature will be disabled and a default value of zero will be used. Possible loss of performance.

©Cummins Inc



19802448

Droop Adjust Potentiometer Circuit

Circuit Description

The droop adjust potentiometer is so the operator can adjust the amount of cross-current compensation the voltage regulator produces when paralleling. The ECM monitors the voltage and expects to see the voltage vary between 0.5 and 4.5 VDC during normal operation. High voltage will trip Fault Code 1412 and can be caused by shorts in the signal wire, an open in the return wire, or a failed potentiometer.

Component Location

Refer to the OEM manual for location.

Shoptalk

Potentiometers are very sensitive to the environment. Clean the potentiometer and check its resistance first.

Refer to Troubleshooting Fault Code t05-1412 (/qs3/pubsys2/xml/en/procedures/01/01-t05-1412.html)

Last Modified: 29-Jul-2010
