

Fault Code: 4688

Water in Fuel Indicator Sensor Circuit - Voltage Above Normal or Shorted to High Source

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 4688 PID(P): SPN: 97 FMI: 3 Lamp: Maintenance SRT:	Water in Fuel Indicator Sensor Circuit - Voltage Above Normal or Shorted to High Source. High voltage detected at the water in fuel indicator circuit.	None on performance. No water in fuel warning available.



QSK19 CM2150 Marine - Water In Fuel Indicator 2 Sensor Circuit

Circuit Description

The water-in-fuel indicator sensor is fitted by the original equipment manufacturer (OEM). The water in fuel indicator 2 sensor sends a signal to the engine control module (ECM) when a set volume of water has accumulated in the fuel filter. The water in fuel indicator 2 sensor circuit contains two wires; a water in fuel indicator RETURN (sensor return 1) ground wire and a water in fuel indicator SIGNAL wire.

Component Location

The water in fuel indicator sensor is mounted by the OEM. Refer to the OEM service manual.

Shoptalk

The water in fuel sensor is integrated into the fuel filter. It is automatically replaced whenever the fuel filter is replaced.

Possible causes for this fault code include:

- Open return or signal circuit in the harness, connectors, or sensor
- SIGNAL wire shorted to sensor supply or battery voltage.

Refer to Troubleshooting Fault Code t05-4688. (</qs3/pubsys2/xml/en/procedures/123/123-t05-4688.html>)

Last Modified: 02-Jan-2017
