



Technical Service Bulletin

Technical Service Bulletin: tsb040034

Released Date: 28-Sep-2004

Loose Gear Cover Spacer Plate Capscrews

Loose Gear Cover Spacer Plate Capscrews

Core Issue

Oil leaks reported coming from the 19 liter engines front gear cover spacer plate due to capscrews becoming loose from gasket relaxation.

Confirmation

This applies to the K19, K19G, QSK19, and QSK19G engines.

Capscrews are becoming loose on the gear cover spacer plate.

None.

Gasket relaxation.

None.

Resolution

When installing gear cover spacer plate capscrews:

- Install a hardened washer, Part Number 3042329, as illustrated in Figure 1. Each capscrew will now have two washers (Figure 1).
- Then apply Loctite™ 271 thread-locker (10 mL [0.338 oz] bottle, Part Number 3824038, or 50 mL [1.69 oz] bottle, Part Number 3375068) to the capscrews, Part Number 3014766) in the method described below.

 GRAPHIC NOT FOUND

Figure 1.

Apply three drops of Loctite™ 271 thread-locker (available as Cummins Inc. service tool part) to each capscrew starting 2 to 3 threads from the tip of the capscrew (12 capscrews on K19, 14 capscrews on QSK19 and QSK19G).

Tighten the capscrews.

Torque Value: 48 n•m [35 ft-lb]

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Last Modified: 28-Sep-2004
