



Technical Service Bulletin

Technical Service Bulletin: tsb100008	Released Date: 11-Feb-2010
Incorrect Torque Converter Orifice Issue	

Incorrect Torque Converter Orifice Issue

Core Issue

This Technical Service Bulletin addresses engines equipped with a torque converter that are experiencing high cooling system pressures, repeat coolant thermostat failures and/or cold cab conditions. For engines equipped with torque converters, an orifice is placed in the bypass hose from the water pump to the thermostat housing which diverts coolant flow to the torque converter. If the incorrect sized orifice is installed, the cooling system pressure can increase above acceptable levels, this can lead to coolant thermostat failures. Due to the high cooling system pressure the rubber on the coolant thermostat degrades, causing the thermostat **not** to seal correctly; this can lead to cold cab conditions.

Note : This is a product improvement and is not subject to TRP or Campaign actions.

Confirmation

ISM, ISMe, QSM11, engines with a build date of January 1, 2007 and later that are equipped with a torque converter.

Symptoms and observations can include high cooling system pressures, repeat coolant thermostat failures, and cold cab conditions. It can also affect EGR cooler coolant flow.

None.

Incorrect orifice installed in the bypass hose between the water pump and the thermostat housing.

None.

Resolution

Verify correct sized orifice for the engine.

Engines built with option TK2012 should have an orifice size of 22.22 mm [0.875 in]. This option is used on engines with EGR.

Engines built with option TK2008 should have an orifice size of 4.75 mm [0.187 in]. This option is used on engines without EGR.

Install correct orifice and replace any damaged components according to warranty guidelines.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Last Modified: 11-Feb-2010
