



Technical Service Bulletin

Technical Service Bulletin: tsb100254

Released Date: 02-Mar-2004

Tube and Shell Heat Exchanger Material Change

Tube and Shell Heat Exchanger Material Change

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin introduces an improved tube material for the tube and shell type heat exchangers used on K19 and K38 engines. Marine, Construction, and Power Generation applications use some or all of the part numbers affected.

The material change is from 90/10 copper nickel to 70/30 copper nickel. The 70/30 copper nickel material allows for longer durability in more corrosive environments.

All of the old part numbers for the heat exchanger cores and assemblies will be superseded for service. Refer to Table 1 for new part numbers.

Table 1, Heat Exchanger Assembly and Core Part Numbers

Description	New Part Number	Superseded Part Number
Assembly, heat exchanger	3968807	3008844
Assembly, heat exchanger	3968809	3011108
Assembly, heat exchanger	3968810	3050385
Core, heat exchanger	3968761	3011327
Core, heat exchanger	3968805	3011326
Core, heat exchanger	3968806	3050384

Note : This is a product improvement, not subject to campaign or Temporary Repair Practice (TRP).