



Technical Service Bulletin

Technical Service Bulletin: tsb100923

Released Date: 03-Jun-2014

Fuel Pump Driveshaft and Press-On Coupling for Severe Duty Applications

Fuel Pump Driveshaft and Press-On Coupling for Severe Duty Applications

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document introduces a change to the CELECT™ fuel pump coupling and driveshaft for severe duty applications.

CELECT™ fuel pumps are driven by a shaft and coupling to produce fuel flow and pressure. In severe duty applications, some CELECT™ fuel pumps exhibit a malfunction where the splines on the driveshaft are worn away and the coupling spins on the shaft. To improve durability and reliability in these instances, a severe duty driveshaft and press-on coupling were released 05-Oct-2009. Refer to Fuel Supply Pump - Rebuild, Service Bulletin 2883495. (</qs3/pubsys2/xml/en/bulletin/2883495.html>)

In addition to the releases of the driveshaft, Part Number 4903252, and the press-on coupling, Part Number 4903253, an alternative to rebuilding a fuel supply pump is available. A CELECT™ service pump, Part Number 4358627Z003, built with the severe duty driveshaft and press-on coupling, was released 12-May-2014.

The release date for the CELECT™ fuel pump with severe duty driveshaft and press-on coupling as an available option for production was 06-Mar-2014.

Pump Assembly		
Part Description	Part Number	
Pump, Gear Fuel	4358627Z003	
Parts Availability Table		
Part Description	Part Number	Service Availability
Driveshaft	4903252	Available
Press-On Coupling	4903253	Available

Document History

Date	Details
2011-3-22	Add link to bulletin 2883495 which the TSB describes.
2012-7-20	Error in original TSB
2014-5-21	none
2014-5-30	outfile

Last Modified: 03-Jun-2014
