



Technical Service Bulletin

Technical Service Bulletin: tsb101723

Released Date: 04-Mar-2010

Revision to Procedure 016-002, Engine Support Bracket, Front

Revision to Procedure 016-002, Engine Support Bracket, Front

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic updates Procedure 016-002 in the Signature, ISX and QSX15 Engines Troubleshooting and Repair Manual, Bulletin 3666239.

The torque procedure and specifications for the front engine support bracket capscrews are being updated to the same procedure and specifications as used at initial engine assembly.

Old Torque Specification	New Torque Specification	Engines Affected
165 N•m [122 ft-lb]	97 N•m + 60 degrees [72 ft-lb + 60 degrees]	Signature, ISX, QSX15

Note : This is a product improvement and not subject to campaign.

Related Procedures

10-016-002-tr (/qs3/pubsys2/xml/en/procedures/10/10-016-002-tr.html)	Engine Support Bracket, Front (/qs3/pubsys2/xml/en/procedures/10/10-016-002-tr.html)
---	---

Last Modified: 04-Mar-2010