



Technical Service Bulletin

Technical Service Bulletin: TSB110191

Released Date: 11-Jul-2011

INSITE™ 7.5 Features and Parameters Issues with QSM11 and QSX15

INSITE™ 7.5 Features and Parameters Issues with QSM11 and QSX15

Core Issue

On QSM11 and QSX15 engines, INSITE™ electronic service tool 7.5.0.234 displays several parameters under Governor Setup as locked and without an ECM Value. These parameters include:

- Breakpoint 1 Speed
- Droop at Breakpoint 1
- Droop at Maximum Throttle
- Droop at Minimum Throttle
- Isochronous Breakpoint Speed

The ECM Values for these parameters are displayed as blank and can **not** be adjusted.

Confirmation

These parameters are locked and do **not** display any ECM Values under Governor Setup.

Resolution

As a work-around, these parameters can be adjusted under the feature Switched Droop\Breakpoint 1.

This issue is under investigation

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Document History

Date	Details
2011-6-24	Module Created

