



Technical Service Bulletin

Technical Service Bulletin: TSB170014

Released Date: 10-Oct-2019

Oversized Cylinder Liners and Shims

Oversized Cylinder Liners and Shims

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK23 CM500

Description of Change

This document announces the release of oversized cylinder liners and shims.

Reason for Change

- The new oversize cylinder liner was released to improve cylinder block serviceability.
- The oversize dimensional feature of the liner applies to the lower press fit diameter **only**.
 - The 0.25 mm [0.0098 in] oversize liner has the lower press fit dimension increased by 0.25 mm [0.0098 in] from its nominal dimensional value.
 - The 0.50 mm [0.0197 in] oversize liner has the lower press fit dimension increased by 0.50 mm [0.0197 in] from its nominal dimensional value.

Service Instructions

Use the following procedure for oversize cylinder liner specifications and removal and installation instructions. See QSK23 Series Engines Troubleshooting and Repair Manual, Bulletin 4021375. Refer to Procedure 001-028 (/qs3/pubsys2/xml/en/procedures/89/89-001-028.html) in Section 1.

Service Parts Availability

Service parts are available. See Table 1 and 2 below for part numbers.

Table 1, Service Parts	
Part Description	New Kit Part Number
0.25 mm [0.0098 inch] Oversize Liner Kit	5405878
0.50 mm [0.0197 inch] Oversize Liner Kit	5405877

Table 2, Service Parts	
Part Description	New Part Number
SHIM [1.50 mm]	3093256
SHIM [0.80 mm]	3093255
SHIM [0.50 mm]	3093254
SHIM [0.26 mm]	3093253
SHIM [0.20 mm]	3093252
SHIM [0.16 mm]	3093251

Part Compatibility

- The new cylinder liners and shims are **not** compatible with existing cylinder blocks.
- The cylinder block **must** be machined to accept the oversized cylinder liner and shims.

Publications Affected

Table 3, Publications Affected					
Manual Type	Engine	Bulletin Number	Procedure Title	Procedure	Section
Service Manual	QSK23 Troubleshooting and Repair Manual	4021375	Cylinder Liner	Refer to Procedure 001-028 (/qs3/pubsyss2/xml/en/procedures/89/89-001-028.html)	1

Document History

Date	Details
2017-1-23	Module Created
2019-5-1	added shim part numbers and references
2019-10-10	Non-Product Problem Solving (PPS)

Last Modified: 10-Oct-2019
