



Technical Service Bulletin: TSB170117

Released Date: 05-Feb-2021

Rocker Lever Ball Fracture and Replacement: Low Power and Engine Smoking

Rocker Lever Ball Fracture and Replacement: Low Power and Engine Smoking

Warranty Statement

The information in this document authorizes specific changes to the repair practice for failures covered under product warranty coverages.

Contents

Product Affected

Engines in mileage ranges as shown below and within build date ranges by plant as shown in Table 1 below are affected.

- 6B, B5.9 (All Versions)
- ISB5.9 (All Versions)
- B6.7 (All Versions)
- ISB6.7 (All Versions)
- ISBe (All Versions)
- ISL (All Versions)
- ISL8.9 (All Versions)
- ISL9 (All Versions)
- ISL9.5 (All Versions)
- ISLE (All Versions)
- L8.9 (All Versions)
- L9 (All Versions)
- L9.3 (All Versions)
- L9.5 (All Versions)
- QSB4.5 (All Versions)
- QSB5.9 (All Versions)
- QSB6.7 (All Versions)
- QSL9 (All Versions)

Table 1, Product Affected by Build Date and Plant		
First Build Date	Last Build Date	Plant
1-June-2017	30-June-2017	Consolidated Diesel Company (Rocky Mount Engine Plant)
17-June-2017	7-July-2017	KCEC (Komatsu Cummins Engine Company)
12-April-2017	12-May-2017	Tata Cummins Limited II (TCL II)
¹ Engine build date can be found on engine dataplate on QuickServe® Online (QSOL).		

Issue

Symptom:

- Low power
- White smoke
- Black smoke
- Abnormal engine noise

Root Cause:

- Fracture of rocker lever ball at interface of shank and flange on rocker lever

Verification

Verify rocker lever ball has fractured at interface of shank and flange on rocker lever. See Figure 1 below.



Figure 1: Rocker Lever Ball Malfunction.

Resolution

- If fracture of rocker lever ball is observed on any rocker lever, all six rocker lever assemblies (containing all twelve individual intake and exhaust rocker levers) **must** be replaced.
- Rocker lever ball malfunction is related to a material issue for a limited rocker lever build period.

Service Parts Availability

Rocker levers are to be replaced with same part number. See Table 2 for part numbers.

Table 2, Service Parts	
Part Description	Existing Part Number
Lever, Rocker	4995602
Lever, Rocker	5253887

Document History

Date	Details
2017-11-9	Module Created
2021-2-5	Removed mileage and hour limitations.

