



Technical Service Bulletin

Technical Service Bulletin: TSB210160

Released Date: 19-Sep-2023

New Flywheel Housing and Rear Crankshaft Seal

New Flywheel Housing and Rear Crankshaft Seal

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK23 CM500
- QSK23 CM2250 K109
- QSK23 CM2350 K127

Description of Change

- Flywheel housing has changed suppliers and has been made common with the Tier 4 product design.
- The rear crankshaft seal bore diameter has changed from 230 mm [9 in] to 200 mm [7.9 in] and requires a new rear crankshaft seal.

Service Instructions

Field repair parts lists for replacement of rear crankshaft seal, see Table 1 and Table 2 below.

Table 1, Parts Matrix 1

FH Option	Flywheel Housing Part Number on Engine	Rear Crankshaft Oil Seal Replacement Part Number	Specific Service Tool Required
FH 5049 (Dry Seal)	4096437	4095800	Refer to Procedure 001-024 (/qs3/pubsys2/xml/en/procedures/89/89-001-024.html)
	4398912	4334444	
FH 5048 (Wet Seal)	4096437	4096506	
	4398912	4367501	

Table 2, Parts Matrix 2			
FH Option	Flywheel Housing Part Number to be Installed	Additional Parts Needed	Specific Service Tool Required
FH 5049 (Dry Seal)	4096437	4095800 – rear crankshaft seal (verify flywheel, Part Number 4096657, is installed)	Refer to Procedure 001-024 (/qs3/pubsys2/xml/en/procedures/89/89-001-024.html)
	4398912	4334444 – rear crankshaft seal	
		4350697 – flywheel	
FH 5048 (Wet Seal)	4096437	4096506 – oil seal (verify flywheel, Part Number 4096657, is installed)	
	4398912	4367501 – rear crankshaft seal	
		4350697 – flywheel	

Service Parts Availability

Service parts are available. See Table 3 for part numbers.

Table 3, Service Parts				
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Oil Seal	4095800	No	No	4334444
Oil Seal	4096506	No	No	4367501
Flywheel Housing	4096437	No	No	4398912
Flywheel	4096657	No	No	4350697

Part Compatibility:

The new rear crankshaft seal has a reduced fitment depth and is **not** backward compatible with the flywheel, Part Number 4096657.

Production Status

Implemented for production. See Table 4.

Table 4, Production Information		
ESN First	Build Date ¹	Plant
85007623	18 May 2020	HHS - CTIL HIGH-HORSEPOWER SEZ
¹ Engine build date can be found on the engine dataplate.		

Publications Affected

Table 5, Publications Affected

Manual Type	Engine	Bulletin Number	Procedure Title	Procedure	Section
Service Manual	QSK23	4021375	Crankshaft Seal, Rear	Refer to Procedure 001-024 (/qs3/pubsyss2/xml/en/procedures/89/89-001-024.html)	1

Document History

Date	Details
2021-7-26	Module Created
2023-9-19	Added QSK23 CM2350 K127 to Product Affected list and tsb metadata.