



Technical Service Bulletin: TSB250174

Released Date: 15-Sep-2025

Water Pump Coolant Leak: New Water Pump Available

Water Pump Coolant Leak: New Water Pump Available

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK23 CM2250 K109
- QSK23 CM2350 K127
- QSK23 CM500

Issue Summary

Symptom:

- External coolant leak from water pump weep hole

Root Cause:

- Contaminants in coolant cause excessive wear on water pump seal creating leak path
- Impeller design creating excessive back pressure on water pump seal bellows creating leak path

Verification

If an engine experiences an external coolant leak from the water pump weep hole and is using the existing water pump part numbers listed in Table 1, reference the resolution section below.

Resolution

- A new water pump assembly is available which uses improved sealing elements and impeller design.
- If an affected water pump part number is found leaking, install the new water pump listed in Table 1. See the corresponding Service Manual. Reference Procedure 008-062 in Section 8.
- **Never** rebuild the existing water pump part number using the new components. The entire water pump assembly **must** be replaced.

Service Parts

Service parts are offered. See Table 1 for part numbers.

Table 1, Service Parts				
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
PUMP, WATER	5580721	Yes	Yes	5611122
KIT, WATER PUMP	5405868	Yes	Yes	5693860

Part Inventory Action

Use existing part number inventory before using new part number.

Production Status

Implemented for production. See Table 2.

Table 2, Production Information		
ESN First	Build Date ¹	Plant
85022010	18 Dec 2024	Phaltan Engine Plant (HHS)
¹ Engine build date can be found on engine dataplate.		

Document History

Date	Details
2025-9-10	Module Created