



Service Bulletin Number: 4358564

Released Date: 06-dec-2013

Asbestos-Containing Gaskets on Cummins China Joint Venture Legacy Product

Asbestos-Containing Gaskets on Cummins China Joint Venture Legacy Product

Introduction

This document outlines a population of legacy engines produced at China Joint Venture engine plants that may have asbestos-containing gaskets. There are a variety of gaskets that have been identified as being at risk. The populations of affected engines are outlined below, along with detailed information about the location and handling of these gaskets.

Engines with gaskets that may contain asbestos should be marked with an "A" (decal Part Number 4326238) to inform the technicians servicing these engines of the possible asbestos-containing gaskets. This document serves as an additional callout of affected engines to provide awareness and safety for individuals servicing the affected engine population.

Safe work procedures for gaskets have been outlined in Safe Work Procedure for Internal Engine and Engine Component Gaskets, Service Bulletin 432604, and Cummins Virtual College course number 1192. Below is an excerpt from the service bulletin that provides further explanation around this issue.

" Rationale : Diesel engines and components contain various types of gaskets. Many engine and component gasket materials are non-fibrous rubber, metal, or silicone; however, some are fibrous and some original equipment manufacturer (OEM), as well as third-party, utilized or owner installed fibrous gaskets may have been manufactured with an asbestos ingredient. Nevertheless, statistical analysis of analogous Cummins® commissioned personal breathing zone airborne asbestos fiber exposure assessments show potential exposures to airborne asbestos fibers are well controlled when good work practices and procedures are used when handling or removing asbestos-containing gaskets.

Note 1: In many countries around the world, gaskets manufactured with an asbestos ingredient (chrysotile) are readily available from third-party vendors, are **not** a regulated product, and may find their way into use on a Cummins® engine.

Note 2: Fibrous looking gaskets that may contain asbestos are **not** able to be confirmed without analytical testing. Testing a gasket to determine its composition is difficult, if **not** impossible, without first disassembling the engine or engine component. However, by following the guidance provided by the Internal Engine and Engine Component Gaskets SWP – Service Centers, the potential for airborne fiber release is minimal."

Quick Reference


Below is a table to direct the user to the appropriate section for more information regarding the type and location of gaskets that may contain asbestos. This lookup table is based on engine serial number (ESN) range and manufacturing plant.

Table 1		
ESN/Date Range		
Plant	DCEC	CCEC
41000000 - 42600429		Section 1
87000000 - 87999999	Section 2	
69000000 - 69999999	Section 2	
41000000 - 41078611		Section 3

Section 1: Chongqing Cummins® Engine Company (CCEC) PT™ Fuel Pump Gasket Care

It has come to the attention of Cummins Inc. that some of the gaskets originally supplied in PT™ Fuel Pumps sourced from China and used in CCEC produced engines (L10, LTA10, M11, NT/NTA 855, KT/KTA/KTTA19, K/KT/KTA 38, KTA50), prior to 31 July 2011, contain some percentage of asbestos. The plant of origin and the manufacturing date of the engine can be obtained from the Engine Serial Number dataplate. Fuel pump serial numbers after 337484 are **not** subject to this notice. Cummins Inc, believes that the encapsulated chrysotile asbestos material present in these gaskets does **not** release asbestos fibers that can be inhaled, and therefore, does **not** present an increased safety risk unless it is handled in such a manner as to abrade, or disturb the integrity of the gasket surface, which could occur during some servicing. We do **not** believe that normal servicing of the PT™ Fuel Pumps sourced from China will cause this to occur. Cummins Inc, has conducted tests which have confirmed our belief that these gaskets can be safely handled and removed. The normal operation of these units does **not** require you to take any additional precautions.

A sample of a typical PT™ fuel pump data tag, from a China sourced PT™ fuel pump, is included below for reference. The fuel pump serial number is the six digit number in the top right corner of the dataplate. The fuel pump with this dataplate was manufactured after the changeover to non-asbestos material.





05y00001

Typical PT™ Fuel Pump Dataplate from a China Sourced PT™ Fuel Pump

Table 2		
Clean ESN	Clean Date	Clean Fuel Pump SN
42600429	31 July 2011	337484

Any used gasket(s) from these units should be disposed of by following all local rules and regulations regarding their disposal.

Section 2: Dongfeng Cummins® Engine Company (DCEC) Air Compressor Gasket Care

It has come to the attention of Cummins Inc. that some of the gaskets originally supplied in Dongfeng pump and Kangtaisi pump air compressors sourced from China and used in DCEC produced engines (B series, C series, L series, ISD, and ISL) prior to 1 July 2011, contain some percentage of asbestos. The plant of origin and the manufacturing date of the engine can be obtained from the Engine Serial Number dataplate. Cummins Inc, believes that the encapsulated chrysotile asbestos material present in these gaskets does **not** release asbestos fibers that can be inhaled, and therefore does **not** present an increased safety risk unless it is handled in such a

manner as to abrade, or disturb the integrity of the gasket surface, which could occur during some servicing. We do **not** believe that normal servicing of the air compressors sourced from China will cause this to occur. Cummins Inc, has conducted tests which have confirmed our belief that these gaskets can be safely handled and removed. The normal operation of these units does **not** require you to take any additional precautions

In summary, the air compressor gasket clean date for DCEC built engines is 1 July 1 2011. ESN clean dates are listed below in Table 3. Any ESNs including and following the ones listed below are asbestos-free.

Table 3		
Clean ESN	Clean Date	Engine Family
87729130	1 July 2011	C, L, and ISL
87233958	1 July 2011	B and ISD

Additional information on the specific gaskets that may contain asbestos for each engine platform is found below in Table 4.

Table 4			
Supplier	Compressor Number	Inner Gasket Number	Engine Series
Dongfeng Pump	4988676	3509DE-086	ISDe
	4947026	3509DE-086	ISDe
	4947027	3509DE2-086	ISDe
	5285436	3509DC2-082	L
	5285437	3509DC2-082	C, L
	3974548	3509H-024	B, ISDe
		3509H-052	
		3509H-069	
		3509H-086	
	4937403	3509H-024	B
		3509H-052	
		3509H-069	
		3509H-086	

Table 4			
Supplier	Compressor Number	Inner Gasket Number	Engine Series
Kangtaisi Pump	3974548	T7551-22Y	B, ISDe
		T7554-32	
		15303-86	
		15301-84	
	3974549	T9059-22Y	B, ISDe
		T9059-32Y	
		15306-42	
		15306-84	
	4933283	T9059-22Y	B
		T9059-32Y	
		15306-42	
		15306-84	
	4937403	T7551-22Y	B
		T7554-32	
		15303-86	
		15301-84	
	4938316	T7551-22Y	B
		T7554-32	
		15303-86	
		15301-84	
	4941224	T9059-22Y	B
		T9059-32Y	
		15306-42	
		15306-84	
	5262642	T8051-22Y	ISDe
		T8651-39	
		23101-91	
		65001-84	
	5274509	T8651-22Y	ISLe
		T8651-32Y	
		49703-84	

Any used gasket(s) from these units should be disposed of by following all local rules and regulations regarding their disposal.

Section 3: Chongqing Cummins® Engine Company (CCEC) Base Engine Gasket Care

It has come to the attention of Cummins Inc. that some of the gaskets originally supplied for use in CCEC produced engines (L10, LTA10, M11, NT/NTA 855, KT/KTA/KTTA19, K/KT/KTA 38, KTA50) prior to 31 July 2006, contain some percentage of asbestos. The plant of origin and the manufacturing date of the engine can be obtained from the Engine Serial Number dataplate. Cummins Inc, believes that the encapsulated chrysotile asbestos material present in these gaskets does **not** release asbestos fibers that can be inhaled, and therefore does **not** present an increased safety risk unless it is handled in such a manner as to abrade, or disturb the integrity of the gasket surface, which could occur during some servicing. We do **not** believe that normal servicing of the engine will cause this to occur. Cummins Inc, has conducted tests which have confirmed our belief that these gaskets can be safely handled and removed. The normal operation of these units does **not** require you to take any additional precautions.

The gaskets that potentially contain asbestos include but are **not** limited to cylinder head gaskets, exhaust manifold gaskets, and turbocharger manifold gaskets. The asbestos-containing gaskets were phased out of use over time, so each engine may have a varying number of gaskets that contain asbestos. Gaskets used in any engine built on or after 31 July 2006 do **not** contain asbestos.

Any used gasket(s) from these units should be disposed of by following all local rules and regulations regarding their disposal.

Document History

Date	Details
2013-12-6	Module Created

Last Modified: 13-Dec-2013
