



Technical Service Bulletin: tsb100044	Released Date: 04-May-2010
Air Compressor Support Brackets Issue	

Air Compressor Support Brackets Issue

Core Issue

The air compressor support brackets (Option CP4073 or CP4076) on QSK19 and K19 engines equipped with twin cylinder air compressor (Part Number 3103409) have been wearing or cracking/breaking. This can result in loss of support for the air compressor and lead to compressor damage. It is recommended that the brackets be checked for wear or cracks at the next regularly scheduled 250 hour maintenance interval.

Confirmation

This issue affects all QSK19 and K19 engines built or upfit with a twin cylinder air compressor, option CP4073 or CP4076. The brackets that have been cracking or showing signs of wear are Part Numbers 4081295 and 4081296.

The issue is noted by wear or fretting between the sleeve and the holes in the brackets. This wear can cause the joint to become loose.

Cracking/breaking of the welds has also been observed.

To verify the malfunction, check the brackets and sleeve for wear. Check the sleeve for grooves or wear marks. Also, check the holes in the bracket for wear or deformation.

Check the welds on the bracket for cracking or other signs of damage.

If any of this is observed, the bracket assembly **must** be replaced.

The cause is suspected to be excessive movement in the bracketry during engine operation. Movement in the bracket causes wear in the sleeve and bracket holes. This wear allows for increased vibration and oscillating load on the bracket and compressor housing.

Bracket cracking/breaking or wear can cause progressive damage to the compressor housing, as seen below. Compressor housings have been found cracked or broken due to lack of support from a worn or broken bracket.

Resolution

Inspect the brackets at the regularly scheduled 250 hour maintenance intervals or during other repairs. If cracking/breaking or wear is seen, the brackets **must** be replaced.



12400064



12400066



Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

