



Technical Service Bulletin

Technical Service Bulletin: tsb100154

Released Date: 30-Apr-2002

New Flywheel Housing

New Flywheel Housing

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service Parts Topic is to inform the field of the introduction of a new flywheel housing for NT855R and N14ER horizontal rail engines.

There have been reports of flywheel housing cracking in high mileage, overhauled engines. This has been seen on some rail applications using remote transmissions. Whilst there is no evidence of this problem with the same flywheel housing used in similar applications throughout the world, to minimize the occurrence of cracks developing, a revised design flywheel housing has been released. The new flywheel housing, Part Number 3287698, obsoletes the old flywheel housing, Part Number 3251848.

The new flywheel housing is similar in appearance to the old flywheel housing. However, the changes to the new flywheel housing include, changes in the material specification to Spheroidal Graphite Cast Iron, and an increase in wall thickness.

NEW	OBSOLETE
3287698	3251848
FH2282	FH11068
FH2282	FH11012

Note : This is a product improvement and is not subject to campaign.

Last Modified: 30-Apr-2002