



Technical Service Bulletin

Technical Service Bulletin: tsb100917

Released Date: 09-Feb-2010

Rear Crankshaft Seal for Dry Flywheel Housing Arrangements

Rear Crankshaft Seal for Dry Flywheel Housing Arrangements

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin identifies a rear crankshaft seal for dry flywheel housing arrangements on some 6C, ISC CM850, ISC CM2150, QSC, ISL CM2150, ISLG, QSL9, C8.3G, C Gas Plus, and L Gas Plus engines that were originally built with a crankshaft seal for wet flywheel housing arrangements.

The option content of FH9523 allowed the assembly of a wet rear seal, Part Number 3911698, into a dry flywheel housing arrangement, Part Number 3911699. The replacement dry rear seal kit is Part Number 3934486.

Engine Serial Number (ESN)	Wet Seal	Dry Seal	Replacement Kit
All	3911698	3911699	3934486

Note : The repair is to replace the rear seal only if required.

The correction was made on October 16, 2009. Engine serial number first (ESN) is 73039070.

TRP 0959 has been published with detailed repair instructions.

Last Modified: 09-Feb-2010