



# Technical Service Bulletin

Technical Service Bulletin: tsb104082

Released Date: 19-Feb-2010

Accessory Drive Procedure, Install Section Revision

## Accessory Drive Procedure, Install Section Revision

### Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

This Service/Parts Topic revises the Install section of Procedure 009-001 (Accessory Drive) in the QSK19 Service Manual, Bulletin 4021592.

This procedure has been revised to allow for the accessory drive to be installed more easily on MRCS engines, as it is **not** necessary to line up the timing marks on the camshaft and camshaft idler gear.

This position of the idler gear does **not** matter when timing the accessory drive. It is **only** necessary to center the timing mark on the camshaft in the upper timing hole and then place the timing mark of the accessory drive gear in the center of the lower timing hole.

This prevents having to bar the engine over multiple times to get the upper timing marks to align.

### Related Procedures

20-009-001-tr  
(/qs3/pubsys2/xml/en/procedures/20/20-009-001-tr.html)

Accessory Drive  
(/qs3/pubsys2/xml/en/procedures/20/20-009-001-tr.html)

Last Modified: 19-Feb-2010