



Technical Service Bulletin

Technical Service Bulletin: TSB104269

Released Date: 21-Dec-2010

Lift Pump Interference Issues

Lift Pump Interference Issues

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document addresses interference issues in the lift pumps for B and C Series diesel engines.

BMC pumps are to be used on Samsung machines due to interference issues. When an interference issue results, use the appropriate BMC pump to resolve the issue. Table 1 lists the supersession from AC Rochester to Federal Mogul (Carter) to BMC pumps. These pumps are a direct supersession on all applications **except** Chrysler.

AC Part Number	FMC Part Number	BMC Pump
3925709	3932224*	N/A
3927153	3932224	N/A
3917998	3932226	3284073
3917999	3932226	3284074
3918000	3932227	3284014
3918076	3932228	3284015
3926034	3932225	N/A
3282870	3932229	N/A
N/A	3932230	N/A

* For Chrysler applications, use Service Kit 3802837 along with lift pump Part No. 3932224. This kit includes a short hose and two clamps. The only hose in this kit is 10 mm [0.39 in] shorter on the fuel heater and strainer side and is only required when changing from the AC Rochester to the Federal Mogul (Carter) lift pump.

The new pump supplier has printed a date code and the last four digits of the Cummins part number on the mounting flange of the pump. The part number is the larger size of the two groups.

Document History

Date	Details
2010-12-21	Module Created

Last Modified: 21-Dec-2010
