



Technical Service Bulletin: TSB110070

Released Date: 17-Mar-2011

New Turbocharger Clamp Plate and Capscrew

New Turbocharger Clamp Plate and Capscrew

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Subject:

Some MidRange, Heavy Duty, and Gas engines operating with wastegate turbochargers can possibly experience exhaust leaks from the turbine and bearing housing mounting joint. This exhaust leak is caused by the mounting capscrews relaxing after operation. New clamp plates and capscrews, which are made of a different material, have been released to correct this issue. This change requires technicians to replace the current clamp plate and capscrews using the repair instructions included in the kit.

Issue:

The typical complaint of this issue is excessive noise due to an exhaust leak. Upon inspection, an exhaust leak is found between the turbine housing and the bearing housing of the turbocharger. The capscrews holding the housings together can possibly be loose or broken.

Verification/Confirmation:

Once it is determined that an exhaust leak exists at the turbine and bearing housing mating joint, check the capscrews for signs of loosening or damage.

Resolution:

Several turbocharger part numbers are affected. Table 1 lists the turbocharger models affected by the new clamp plate and capscrews. Installation instructions are included in the new kits.

Table 1: New Clamp Plate and Capscrew Kits		
	Turbocharger Model	New Clamp Plate and Capscrew Kit Number
MidRange/Gas	H1C	4032887
	H1E	4032887
	WH1C	4032887
	WH1E	4032887
	HX35	4032887
	HX35W	4032887
	HX35G	4032887
	HX40	4032887
	HX40W	4032887
	HX40G	4032887
	HE351	4032887
	HE351W	4032887
Heavy Duty	HX50	4032877
	HX50W	4032877
	HX55	4032877
	HX55W	4032877


--

Table 2: Contents of Kits				
Kit	Part Number Included in Kit	Description	Quantity	Available for Purchase (Y/N)
4032887		Kit, Turbocharger Repair	1	Y
	2839879	Clamping Plate	2	N
	2840781	Capscrews	6	N
	3535215	Boost Clip	1	Y
	4029685	Installation Instruction Sheet	2	N
4032877		Kit, Turbocharger Repair	1	Y
	2840780	Clamping Plate	3	N
	2840781	Capscrews	6	N

Table 2: Contents of Kits				
Kit	Part Number Included in Kit	Description	Quantity	Available for Purchase (Y/N)
	3535215	Boost Clip	1	Y
	4029684	Installation Instruction Sheet	1	N

10v00002

MidRange - Old Clamp Plate and Capscrews - Silver in Color/Stainless





10v00004

Heavy Duty - Old Clamp Plate and Capscrews - Silver in Color/Stainless



10v00003

MidRange - Black Oxide Clamp Plates with B16 Material Capscrews - Included in Kit 4032887



10v00005

Heavy Duty - Black Oxide Clamp Plates with B16 Material Capscrews - Included in Kit 4032877

Document History

Date	Details
2011-3-10	Module Created
2011-3-17	QSOL Quick Fix Reason: Format Error Notes: none

Last Modified: 17-Mar-2011
