



Technical Service Bulletin

Technical Service Bulletin: TSB110155

Released Date: 16-May-2011

White Smoke When Warm

White Smoke When Warm

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document was originally released between 1994 and 2001. It has been added to QSOL for informational purposes

This document provides new fuel pump calibration information for Bosch® fuel pumps. This new calibration addresses complaints of white smoke under hard acceleration after the engine reaches operating temperature. White smoke is still to be expected when engine is **not** up to operating temperature.

Remove the pump and take it to the local Bosch® authorized repair facility. If the ADS location does **not** have the specification they should call the Bosch® Tech Support line in Broadview for the specification. The Bosch® will invoice the Cummins repair location for the re-calibration. File the Bosch® charge and the R&I of the pump under standard warranty.

The pumps should be calibrated to test specifications as follows:

Pump Part Number	Revision Number	Revision Date
3921922	12 or higher	August 4, 1997 or later
3928147 or later	7 or higher	July 30, 1997 or later

Document History

Date	Details
2011-5-16	Module Created

Last Modified: 16-May-2011

