



Technical Service Bulletin

Technical Service Bulletin: TSB120182	Released Date: 12-Feb-2013
DEF Pump Override Test Error - The engine control module has detected a condition that would not let the DEF Override Test run	

DEF Pump Override Test Error - The engine control module has detected a condition that would not let the DEF Override Test run

Core Issue

Users are unable to run the Diesel Exhaust Fluid (DEF) Pump Override Test in INSITE™ electronic service tool. The message, which is displayed in the status box within the test, states “ECM detected a condition that would not let the DEF override test run”. INSITE™ electronic service tool does **not** provide information on what the condition is, therefore the technician does **not** know what to fix for the test to run.

Confirmation

Users may see the error when they try to run the DEF Pump Override Test.

Resolution

Verify there are **no** active fault codes. If there are active fault codes, troubleshoot those accordingly. After all fault codes are addressed and the DEF Pump Override Test is required, follow the directions below:

- Disconnect INSITE™ electronic service tool
- Turn keyswitch OFF
- Wait 90 seconds (time for all devices to shut down)
- Turn keyswitch ON (wait between 90 seconds and 2 minutes to make sure everything is started and ready for operation.)
- Connect INSITE™ electronic service tool and run the DEF Pump Override Test.

To permanently address this issue; a 90 second delay was added to delay the start of the Diesel Exhaust Fluid (DEF) Pump Override Test after the “Start” button is selected. This 90 second delay will allow the engine to reach its prime start condition and will then allow the test to begin. This fix is included in INSITE™ electronic service tool, version 7.6, which was released on 23 October 2012.

Also, a notification was implemented to alert the user of missing engine states status' detected by INSITE™ electronic service tool. This fix is available in INSITE™ electronic service tool, version 7.6.1, which was released on 30 January 2013.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Document History

Date	Details
2012-5-17	Module Created
2013-2-12	To announce production relase dates for the step 6 fix of INSITE%u2122

Last Modified: 12-Feb-2013
