



Technical Service Bulletin

Technical Service Bulletin: TSB120277

Released Date: 23-Oct-2012

QSK19 Modular Common Rail System (MCRS) Engine with Fault Code 285

QSK19 Modular Common Rail System (MCRS) Engine with Fault Code 285

Core Issue

A customer complaint has been received for Fault Code 285 being active or high counts of it inactive. A calibration error was made on some calibrations, which set Mux_Timeout_Fault_Count to 500 milliseconds [.50 seconds] which equals the transmit rate and causes false fault codes.

This issue has been seen on Phase 18 software for CM850 engines and Phase 25 for CM2150 engines.

Confirmation

- Verify that the J1939 Multiplexing is enabled.
- Verify that the Mux_Timeout_Fault_Count is set to 500 milliseconds [.50 seconds] using Calterm. If it is set to greater than 2,000 milliseconds [2.0 seconds] then disregard this document and continue with normal fault code troubleshooting steps.

Resolution

The engine control module (ECM) **must** be calibrated with the latest calibration available on the INCAL™ disc. This should change the Mux_Timeout_Fault_Count to be set to greater than 2,000 milliseconds [2.0 seconds]. If it is still set to 500 milliseconds [.50 seconds] or a fault still occurs, follow the factory normal escalation process for Cummins, Inc.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Document History

Date	Details
2012-10-18	Module Created

