



Technical Service Bulletin

Technical Service Bulletin: TSB140110	Released Date: 05-Sep-2014
11-SI Alternator Front Bearing Malfunctions on 6C8.3 Tier 1 Engines Causing Difficulty Starting the Engine or Noise Complaints.	

11-SI Alternator Front Bearing Malfunctions on 6C8.3 Tier 1 Engines Causing Difficulty Starting the Engine or Noise Complaints.

Core Issue

Issues with 11-SI alternators have been observed on rental power generation units. Customers experience difficulty starting the engine or noise complaints. Upon investigation, it's found the alternator is **not** properly charging the battery due to the alternator bearing being seized. This occasionally also causes progressive damage to the alternator pulley and the belt. The failure mode is internal bearing damage from water intrusion during power washing. Power washing 11-SI alternators can cause bearing damage.

Confirmation

11-SI alternators with bearing damage from power washing will cease to function. It will not spin freely or may not spin at all. The bearing(s) may be damaged to the extent that the shaft is no longer centered in the bearing (see photograph below).

Resolution

The best way to avoid this situation is to **not** power wash near the alternator. If power washing is necessary in this area, be sure to provide ample water protection for the alternator.



13500025

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Document History

Date	Details
2014-8-20	Module Created

Last Modified: 05-Sep-2014
