



Technical Service Bulletin

Technical Service Bulletin: TSB160117

Released Date: 14-Nov-2016

Fan Spacer Mounting Capscrew Malfunction

Fan Spacer Mounting Capscrew Malfunction

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- NTA-855-C (Industrial applications **only**)

Issue

Symptom:

- Fan spacer mounting capscrews loosen with normal engine operation.

Root Cause:

- Insufficient length of fan spacer mounting capscrews.

Verification

- Verify fan spacer mounting capscrews are loose.

Resolution

- New fan spacer mounting capscrews 11.4 cm [4.50 in] in length have been released. Existing fan spacer mounting capscrews are 10.2 cm [4.00 in] in length.
- Replace existing fan spacer mounting capscrews with new capscrews. See Table 1 below for part numbers.

Service Parts Availability

Service parts are available. See Table 1.

Table 1, Service Parts

Part Description	Existing Part Number	Obsoleted	Superseded	New Part Number
Screw, Hexagon Head Cap	108603	No	No	108604

Production Status

Table 2, Production Information			
Product	Engine Serial Number (ESN) First	Build Date*	Engine Plant
NTA-855-C	25420584	26 September 2016	KCL - INDIA, LTD.
*Engine build date can be found on the engine data plate			

Document History

Date	Details
2016-10-28	Module Created

Last Modified: 14-Nov-2016
