



Technical Service Bulletin

Technical Service Bulletin: TSB170039

Released Date: 12-Apr-2017

Implementation of Starting Motor and Automatic Starting Control

Implementation of Starting Motor and Automatic Starting Control

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

This TSB **only** applies to the below engine produced in India:

- NTA-855-C (Construction applications **only**)

Issue

Symptom:

- Engine will **not** start.

Root Cause:

- Starting motor malfunction caused by engine over cranking, low battery voltage, improper cranking circuit, and excess heating of starting motor.

Resolution

- New engines are now built with a more robust starting motor and automatic starting control unit. The automatic starting control unit prevents engine over cranking and low battery voltage.

Service Parts Availability

Service parts are available. See Table 1.

Table 1, Service Parts

Part Description	Existing Part Number	Obsoleted	Superseded	New Part Number
Motor, Starting	5278095	No	Yes	3636821
Control, Aut Starting	-	No	No	2868589

Production Status

Table 2, Production Information

Product	Engine Serial Number (ESN) First	Build Date*	Engine Plant
NTA-855-C	25414983	06 February 2016	KCL - INDIA, LTD. (Cummins India Ltd.)**
*Engine build date can be found on the engine data plate			
**Engine manufacturing plant can be found on the engine data plate			

Document History

Date	Details
2017-3-28	Module Created

Last Modified: 12-Apr-2017