



Technical Service Bulletin

Technical Service Bulletin: TSB200209

Released Date: 23-Apr-2021

New Lead-Free Connecting Rod Bearing

New Lead-Free Connecting Rod Bearing

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- ISC CM2150
- ISC8.3 CM2250
- ISL CM2150
- ISL8.9 CM2150 L110
- ISL8.9 CM2880 L112
- ISL9 CM2150 SN
- ISL9 CM2250
- ISL9 CM2350 L101
- ISL9 CM2350 L111
- ISLe CM2150
- L8.9 L121
- L9 CM2350 L116B
- L9 CM2350 L119B
- L9 CM2350 L120C
- L9 CM2350 L123B
- L9 CM2350 L129C
- L9 CM2350 L133C
- L9 CM2450 L126B
- L9 CM2670 L128B
- QSC8.3 CM2880 C102
- QSL9 CM2250
- QSL9 CM2250 L115
- QSL9 CM2350 L102
- QSL9 CM2350 L107
- QSL9 CM2350 L118
- QSL9 CM2350 L122
- QSL9 M CM2250 L106

Description of Change

This document announces the release of new lead-free connecting rod bearings.

Beginning in June 2020 some engines for non-stop-start applications began manufacturing with different connecting rod bearings.

Note : This TSB does not apply to stop-start applications. Reference parts.cummins.com for supersession/replacement connecting rod bearings for stop-start applications.

Key differences:

- Released bearing material offers more debris robustness
- Connecting rod bearings will have a dark grey overlay
- Connecting rod bearings will have staked tang design and ID bar-codes

Reason for Change

- New lead-free rod bearings were developed to improve debris robustness.

Service Instructions

- Due to overlay oxidation, upper connecting rod bearing may appear green. See Figure 1. This is **not** considered detrimental for bearing durability or performance. Follow existing service guideline for re-use criteria.
- Existing and new part numbers are **not** to be mixed, upper and lower rod bearings **must** be replaced as a set.



Figure 1, Green appearance of upper connecting rod bearing, Part Number 5566472, due to overlay oxidation.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number for Non Stop-Start Applications Only
Upper connecting rod bearing	5283365	Yes	Yes	5566472
Lower connecting rod bearing	5283364	Yes	Yes	5566471

Part Identification

- Connecting rod bearings can be identified by their part numbers. See below.

New Upper Rod Bearing, Part Number 5566472.



Figure 2, 5566472 ID Appearance, OD Appearance, Part Number Stamping.

New Lower Rod Bearing, Part Number 5566471.



Figure 3, 5566471 ID Appearance, OD Appearance, Part Number Stamping.

Part Inventory Action

- Use existing part number inventory before using the new part number.
- Do **not** mix old and new rod bearings between cylinders for individual engines.

Associated Publications

Manual Type	Procedure Title	Procedure
Service Manual	Bearings, Connecting Rod	001-005

Document History

Date	Details
2020-10-16	Module Created
2021-4-23	Updated Description of Change to include note for stop-start applications.