



Technical Service Bulletin

Technical Service Bulletin: tsb060006	Released Date: 08-Mar-2006
Fan Hub Locknut	

Fan Hub Locknut

Core Issue

The purpose of this Early Notification is to inform the field service locations of possible loose fan hub locknuts, Part Number 3171137, on QSK45 and QSK60 engines.

Confirmation

QSK45 and QSK60 engines built after 16-September-2005 with the following options:

- FA6165
- FA6189
- FA6190
- FA6191
- FA6196

Could possibly experience fan hub vibrations leading to loosening of the fan belt pulley. Inspect for twists or cracks in the fan belt.

None.

Under investigation.

Loss of engine cooling capability and possible damage to the fan and radiator.

Resolution

1. Order quantity one locknut, Part Number 3171137.
2. Remove grease over the original locknut.
3. Remove the installed locknut.
4. Remove the existing lock washer, Part Number 4000744, and discard.
5. Install the original locknut. Make sure that the original locknut has the chamfer facing away from the spacer washer (which can be seen right behind the locknut).
6. Torque the original locknut to 600 N•m [443 ft-lb].
7. Apply Loctite 648 to the second locknut.
8. Install the second locknut over the shaft with the chamfer facing towards the chamfer on the previously installed locknut.
9. Torque the second locknut to 250 N•m [184 ft-lb].
10. Make sure that approximately 300 cc of grease (Mineral oil grease CES20014) is filled into the cavity around the locknut before installing the cover.

11. Install the o-ring into the groove in the spacer mounting end cover and lightly lubricate the o-ring. The spacer can be pushed fully home into the fan hub before tightening the capscrews. Tighten the capscrews to 280 N•m [207 ft-lb].

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Last Modified: 08-Mar-2006
