



Technical Service Bulletin

Technical Service Bulletin: tsb070004

Released Date: 22-Jan-2007

Possible Oil Leaks - Wet Flywheel Housings

Possible Oil Leaks - Wet Flywheel Housings

Core Issue

The purpose of this Early Field Notification is to inform the field of possible oil leaks from a threaded mounting hole on wet flywheel housings installed on QSK45 and QSK60 engines.

Confirmation

QSK45 Engines with Option FH 6047

QSK60 Engines with Option FH 6047

An oil leak at the second from the top, rear threaded hole, on the wet flywheel housing may be observed from the mounting pad on the left side of the flywheel housing.

None.

The threaded mounting hole was drilled too deep when the flywheel housing was machined.

Loss of performance, premature wear, or damage to components inside the wet flywheel housing.

Resolution

1. Order quantity one, M20 X 2.5-6g threaded capscrew. Make sure the capscrew has at least 38 mm [1.5 in.] of thread.
2. Cut off the head of the capscrew so that the threaded half of the capscrew is between 25.4 mm [1 in.] and 32 mm [1.25 in.] long. Discard the head.
3. Grind a slot in the cut off end of the capscrew, such that it can be turned with a flat screwdriver.
4. Clean the threaded hole of the flywheel housing with brake cleaner, and dry with compressed air.
5. Apply a standard Stud Lock Loctite® to the remaining piece of the capscrew threads.
6. Install the remaining piece of the capscrew into the threaded hole of the flywheel housing until snug.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

