



Technical Service Bulletin

Technical Service Bulletin: tsb080080	Released Date: 25-Apr-2012
Oil Cooler Cover Nut Gasket Leaks	

Oil Cooler Cover Nut Gasket Leaks

Core Issue

Some QSK45, QSK60, QSK78, and QSK60G engines are experiencing slow leaks at the oil cooler cover nut gasket, Part Number 3630969. For clarification, this gasket seals the large oil cooler studs. This is **not** the oil cooler plate gasket.

Confirmation

QSK45, QSK60, QSK78, and QSK60G engines.

This issue can result in a slow external coolant leak.

There will be signs of engine coolant on top of the oil cooler cover around the large oil cooler nuts.

Still under investigation.

There is no potential for component damage.

Resolution

Replace the paper gasket, Part Number 3630969, with an edge-molded gasket, Part Number 3637730. Additionally, use Loctite™ 271, Part Number 3375068, on the oil cooler stud threads.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Last Modified: 25-Apr-2012
