



Technical Service Bulletin

Technical Service Bulletin: tsb100135

Released Date: 01-Oct-2001

New Cavitation Fix Injector

New Cavitation Fix Injector

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin introduces a new cavitation fix injector for QSK45 and QSK60 engines.

The new injector has been redesigned to address the injector cavitation issue that has been seen in some high-horsepower applications. The new injectors will supersede the present injectors and will have new part numbers. Table 1 provides the supersession matrix.

The new cavitation fix injectors are transparent to the field and can be used in combination with the older part numbers in the same engine. A calibration change is **not** necessary.

The new injectors are presently used in production and can be identified by the part number inscribed on the top stop housing. Use Fig. 1 for the location of the part number.



06600107

Fig. 1, Location of New Stamped Part Number

Table 1, Injector Supersession Parts Matrix

Old Injector Part Number	New Injector Part Number	Affected PP Options and CPLs	Detail
4010025	4087893NX	2820, 2821, 2823, 2824, 2848, 2849, 2850, 2851, 2854	QSK45 and QSK60 high BMEP ¹
4010158	4087892NX	2469, 2853, 2855, 2948	QSK45 and QSK60 low BMEP ¹
4010160	4087894NX	2655, 2656, 2665, 2666, 2667, 2887, 2888, 2920, 2935	QSK45 and QSK60 power generation

¹BMEP = Brake Mean Effective Pressure