



Technical Service Bulletin

Technical Service Bulletin: tsb100178

Released Date: 28-Aug-2002

Cylinder Head Gasket Change

Cylinder Head Gasket Change

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Note : This Technical Service Bulletin supersedes 01T2-9 and 02T2-2; replace 01T2-9 and 02T2-2 with this topic.

This Technical Service Bulletin introduces a change made to the QSK45 and QSK60 series engines cylinder head gasket.

The cylinder head gasket now has an improved coating made of aluminium that helps to prevent degradation/corrosion of the steel carrier. The new gasket, Part Number 4086225, also incorporates previous improvements made to the component, which includes a change in material used for the cooling grommets in order to improve temperature capability, and an increase in the thickness of the seven head bolt hole grommets to improve sealing. It is visibly identifiable from the previous versions by its aluminium surface finish and colour.

The new cylinder head gasket went into production at the Daventry Engine Plant in July 2002, with engine serial number 33152354.

Inclusion of Improvements Made to Gasket

Part Number	Version	Gasket Status	Coolant Grommets	Head Bolt Grommets	Aluminium Coating
3410963	1	Old	No	No	No
4066243	2	Old	Yes	No	No
4080532	3	Old	Yes	Yes	No
4086225	4	New	Yes	Yes	Yes

Note : This is a product improvement and is not subject to campaign.

