



Technical Service Bulletin: tsb100197

Released Date: 20-Feb-2003

Fuel Shutoff Valve (FSOV) Actuator Housing and Disc

Fuel Shutoff Valve (FSOV) Actuator Housing and Disc

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin introduces a change to the QSK45 and QSK60 fuel shutoff valve (FSOV).

The first engine serial number is 33153255, built July 1, 2002.

Engine shutdown and low power issues on some engines have been due to the fuel shutoff valve (FSOV) blow-shut condition. When the fuel heats up, the thermal growth mismatch of the fuel shutoff valve (FSOV) housing and the actuator disc allows fuel to the backside of the disc. The control volume pressure causes the actuator disc to blow shut.

To reduce the thermal growth mismatch, the actuator housing, Part Number 3417102, made of anodized aluminum, **must** be replaced with Part Number 4088273, made of 303 stainless steel with nickel plating. The actuator disc, Part Number 3408424, **must** be replaced by Part Number 4088274, which has a different geometry to reduce control volume pressure.

The fuel shutoff valve (FSOV) assembly part number has **not** been changed.

Actuator housing, Part Number 3417102, and actuator disc, Part Number 3408424, are **not** superseded due to their continued use on the QSK19, which has a reduced flow rate when compared to the QSK45 and QSK60.