



Technical Service Bulletin

Technical Service Bulletin: tsb100232

Released Date: 15-Sep-2003

Lubricating Oil Pump Tube Introduction and Modification

Lubricating Oil Pump Tube Introduction and Modification

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service parts topic is to introduce the new lubricating oil pump part number 4100710 which obsoletes and supersedes part number 4066027 on QSK45 engines and lubricating oil pump part number 4100711 which obsoletes and supersedes part number 4065652 on QSK60 engines.

Engine Serial Number (ESN) first:

Part Number 4100710, 33153112 built December 2002.

Part Number 4100711, 33154182 built June 2003.

The drive ratio has been changed from 1.2 to 1.3 to improve performance at lower speeds and also communizes it with the QSK78 pump. The regulator port size and regulator spring rate has been changed to reduce parasitic losses. A deflector plate discharges the pressure regulator outlet into the sump to reduce aeration. There is no longer a high-pressure relief valve and the gear cover is now a formed one-piece cover.

The discharge port has been revised and a single piece discharge tube **must** be used.

The table below lists the additional parts that **must** be ordered when upfitting lubricating oil pump part number 4065651 with lubrication oil pump part number 4100710 on QSK45 engines.

On QSK60 engines, upfit with lubricating oil pump part number 4065652 with lubricating oil pump part number 4100711.

Additional needed parts:

Part Number	QTY	Description
4066383	1	TUBE, LUB OIL TRANSFER
3089886	2	SEAL, RECTANGULAR RING
3902460	6	SCREW, HEX FLANGE HEAD CAP

4066672	1	BRACKET, OIL TUBE
3902460	2	SCREW, HEX FLANGE HEAD CAP
3902662	2	NUT, HEXAGON FLANGE
3903990	2	SCREW, HEX FLANGE HEAD CA
4017285	1	CLAMP, TUBE

Note : This is a product improvement and not subject to campaign or TRP.

Last Modified: 15-Sep-2003
