



Technical Service Bulletin

Technical Service Bulletin: tsb100262

Released Date: 22-Mar-2004

Engine Hours Broadcast

Engine Hours Broadcast

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin informs field service of software phase compatibilities with engine hour monitoring devices using a datalink broadcast to J1939 and J1587/1708.

This Technical Service Bulletin also informs field service of engine hour offset monitoring capabilities via datalink.

Engine hours broadcast via J1587/J1708 is **only** available with calibrations of software Phase 5.9.5.4 or higher.

Engine hours broadcast via J1939 is **only** available with calibrations of software Phase 5.9.7.1 or higher.

Calibration software phases can be monitored and identified via Insite™ 6.2.

Phase 5.9.7.1 software will be available middle-2004. Calibrations will be upgraded accordingly.

After replacing an ECM, the engine hours+offset are read as total engine hours when using Insite™.

Note : When reading engine hours via the datalink, the offset will **not** be added to the engine hours.

Note : Insite™ can monitor engine hours on all QSK19 calibrations.

Software Broadcast Limitation Matrix				
Broadcast Link	Software Phase 2.7	Software Phase 5.9.5.4	Software Phase 5.9.6.11	Software Phase 5.9.7.1 (Release Middle-2004)
J1587 / J1708	No	Yes	Yes	Yes / or higher
J1939	No	No	No	Yes / or higher

