



Technical Service Bulletin

Technical Service Bulletin: tsb100642

Released Date: 08-Nov-2007

New Piston

New Piston

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin introduces new Ferrous Cast Ductile (FCD) single-piece, cast iron pistons for the QSK45 and QSK60 engines.

The new FCD piston is being released to improve scuff resistance during cold starts where the ambient temperature is below -4°C [25°F]. The new FCD piston has a revised skirt profile that reduces the contact pressure between the piston and liner during cold start conditions. The tables below outline the old part numbers and options affected for the High BMEP (Brake Mean Effective Pressure), Low BMEP, and TA Luft pistons. There is no restriction in using this new FCD piston with the old FCD piston design.

It is still recommended for the cold climates to use preheating instructions put forth in the Early Field Notification Number E07020.

The Engine Serial Number (ESN) first for production is 33171052, built November 5, 2007.

Table 1, High BMEP Pistons and Service Kit

	Old Part Numbers	New Part Numbers
Piston	4066543	3640474
Piston TLA	3410649	3640522
Piston TLA	4097888	3640523
Service Kit	4089246	4955781

PP Options Affected		
PP 2655		
PP 2656		
PP 2666		
PP 2667		
PP 2820		
PP 2821		
PP 2823		
PP 2824		
PP 2848		
PP 2849		
PP 2850		
PP 2851		
PP 2854		
PP 2888		
PP 2920		
PP 2935		
PP 6829		
PP 6835		
PP 8156		
PP 8294		
PP 8336		
PP 8613		
PP 8617		
PP 8694		
PP 8696		
PP40705		
PP41795		
PP42622		
PP 6815		
Table 2, Low BMEP Pistons and Service Kit		
	Old Part Numbers	New Part Numbers
Piston	4066551	3640512
Piston TLA	3410648	3640521
Service Kit	4089268	4955782

PP Options Affected		
PP 2469		
PP 2853		
PP 2855		
PP 2948		
PP 8155		
Table 3, TA Luft Pistons and Service Kit		
	Old Part Numbers	New Part Numbers
Piston	4067004	3640513
Piston TLA	4001075	3640520
Service Kit	4089269	4955783
PP Options Affected		
PP 8295		