



# Technical Service Bulletin

Technical Service Bulletin: tsb100708

Released Date: 03-Apr-2014

Lubricating Oil Pump Rebuild Parts Announcement

## Lubricating Oil Pump Rebuild Parts Announcement

### Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

This Parts Announcement supersedes 02T7-8, please replace 02T7-8 with this topic. This parts announcement provides tables listing the common parts used to rebuild the lubricating oil pump for the QSK45 and QSK60 series engines. If a pump does **not** have a pressure relief valve, it is recommended that the pump be replaced with one that has an integrated high pressure relief valve. Part numbers and engine serial number (ESN) first are in Table 3 below.

**Table 1, QSK45 and QSK60 Lubricating Oil Pump Rebuild Kit**

| Part Number | Description                       | Quantity |
|-------------|-----------------------------------|----------|
| 4066547     | Idler shaft kit                   | 1        |
| 4016829     | Ball bearing                      | 1        |
| 4016842     | Suction head to housing gasket    | 1        |
| 3900631     | Capscrew M8                       | 3        |
| 3901249     | Capscrew M12                      | 1        |
| 4065666     | High pressure relief valve spring | 1        |
| 3635142     | Pressure regulator spring         | 1        |
| 4016948     | Poppet spacer                     | 1        |
| 4016827     | Snap ring                         | 1        |
| 3635141     | Pressure regulator valve          | 1        |

**Table 2, Items used with QSK45 and QSK60 Lubricating Oil Pump Rebuild Kit, Purchased Separately**

| Part Number | Description      | Quantity |
|-------------|------------------|----------|
| 4016659     | Discharge tube   | 1        |
| 3089886     | Rectangular seal | 2        |

| Table 2, Items used with QSK45 and QSK60 Lubricating Oil Pump Rebuild Kit, Purchased Separately |                          |                 |           |
|-------------------------------------------------------------------------------------------------|--------------------------|-----------------|-----------|
| Part Number                                                                                     | Description              | Quantity        |           |
| 3089891                                                                                         | Rectangular seal         | 1               |           |
| 4016660*                                                                                        | Shim, 0.13 mm [0.005 in] | 2               |           |
| 4016661*                                                                                        | Shim, 0.25 mm [0.010 in] | 2               |           |
| * Shims to be used <b>only</b> when the pump housing is to be replaced.                         |                          |                 |           |
| Table 3, New Part Number for Lubricating Oil Pump with High Pressure Relief Valve               |                          |                 |           |
| Engine                                                                                          | Old Part Number          | New Part Number | ESN First |
| QSK45                                                                                           | 4100710                  | 3638986         | 33164296  |
| QSK60                                                                                           | 4100711                  | 3638987         | 33164290  |

## Document History

| Date      | Details |
|-----------|---------|
| 2014-3-31 | none    |