



Technical Service Bulletin

Technical Service Bulletin: TSB100983

Released Date: 27-Sep-2010

New QSK45 / 60 Turbochargers Fitted With A286 Turbine Housing Capscrews

New QSK45 / 60 Turbochargers Fitted With A286 Turbine Housing Capscrews

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

New turbochargers have been released for QSK45 and QSK60 industrial engine applications. These new turbochargers are specified with A286 stainless steel capscrews to retain the turbine housing to the bearing housing of the turbocharger.

See table below for old and new turbocharger part numbers and old and new turbocharger service kit part numbers.

	Not For Sale		For Sale			
	Old Tur boc harg er Part Nu mbe r	New Tur boc harg er Part Nu mbe r	Old Tur boc harg er Part Nu mbe r	New Tur boc harg er Part Nu mbe r	Old Tur boc harg er Serv ice Kit Part Nu mbe r	New Tur boc harg er Serv ice Kit Part Nu mbe r
Engi ne Mod el						

QSK 45	283 473 7	376 751 3	403 347 3	Ord er old Part Nu mbe r (see Not e1)	380 085 1	Ord er Old Part Nu mbe r (see Not e 1)
	283 752 5	376 751 4	403 278 9	Ord er Old Part Nu mbe r (see Not e 1)	495 614 2	Ord er Old Part Nu mbe r (see Not e 1)
	283 752 2	376 751 5	403 373 6	Ord er Old Part Nu mbe r (see Not e 1)	288 192 2	Ord er Old Part Nu mbe r (see Not e 1)
	404 403 3	To Be Dete rmin ed (see Not e 2)	403 303 8	Ord er Old Part Nu mbe r (see Not e 1)	495 539 2	Ord er Old Part Nu mbe r (see Not e 1)

QSK 60, 2 Stag e (Hig h Pres sure Turb och arge rs)	N/A	N/A	359 792 7	284 058 5	408 912 6	288 181 6
QSK 60 MC RS, 2 Stag e (Hig h Pres sure Turb och arge r	N/A	N/A	404 477 0	284 058 4	495 550 3	288 181 7
QSK 60; Sing le Stag e	N/A	N/A	403 596 5	404 729 1	408 975 6	495 568 6
	N/A	N/A	404 178 7	404 729 1	495 518 8	495 568 6
	N/A	N/A	359 632 3	494 729 8	402 535 0	495 568 9

QSK 60 MC RS, Sing le Stag e	N/A	N/A	404 637 1	404 729 4	N/A	495 568 0
	N/A	N/A	404 637 3	404 729 5	N/A	495 568 1
	N/A	N/A	404 319 8	404 729 6	N/A	495 564 7
	N/A	N/A	404 729 2	404 729 6	495 568 8	495 564 7
	N/A	N/A	404 321 6	404 729 7	N/A	495 564 8
	N/A	N/A	404 729 3	404 729 7	495 568 7	495 564 8

Note 1: The old turbocharger and old turbocharger service kit part numbers are available for sale and have been updated to include a turbocharger assembly with the new A286 capscrows.

Note 2: Part Number 4044033 is still awaiting the introduction of this change. Further updates will be published when this action is complete. In the interim, for repairs to engines where this turbocharger is fitted, the Service Kit, Part Number 4032182, **must** be ordered to allow the new capscrows to be installed.

This Service Kit, Part Number 4032182 (includes eight of the new A286 capscrows and four lockplates) is still available and **must** be used on repairs where turbocharger replacement is **not** required.

Note: The replacement of the capscrows **must not** be attempted as an in-chassis repair.

The new turbochargers have been implemented in production with the following Engine Serial Number (ESN) firsts.

Engine Model	ESN First
QSK45	33182922
QSK60 Single Stage	33168646
QSK60 2 Stage	33179762
QSK60 MCRS 2 Stage	33179510

The torque specification for the capscrows and the installation procedure remain unchanged.

Document History

Date	Details
2010-7-23	Module Created

Last Modified: 27-Sep-2010
