



Technical Service Bulletin

Technical Service Bulletin: tsb101223

Released Date: 19-Mar-2004

Aftercooler Core Weld Location Change

Aftercooler Core Weld Location Change

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic supersedes 00T10-4 and 02T10-3. It introduces a change made to the aftercooler core on the QSK60 Engine and is divided into four sections:

1. New Parts Introduction
2. Compatibility Matrix
3. Machine Procedure
4. Old Aftercooler Core Reuse Guidelines.

The following changes were made to the original aftercooler core in order to improve its strength and durability:

1. Relocation of the aftercooler core capscrew mounting holes inboard of the flange-forming notch. This is similar in design to the QSK45, K38, and K50 products.
2. A 30 percent increase in the flange thickness. The old flange was 3.42 mm [0.135 in] and the new flange is 4.55 mm [0.179 in] thick.

This aftercooler core, Part Number 4080568, is referred to in this service/parts topic as *revision 1*.

The *revision 1* aftercooler core went into production at the Daventry Engine Plant with engine serial number 33150882.

A second revision with the following change has now been made to the aftercooler core:

- Relocation of the flange welds back to their original position.

This aftercooler core, Part Number 4100636, is referred to in this service/parts topic as *revision 2*.

The *revision 2* aftercooler core went into production at the Daventry Engine Plant with engine serial number 33152630.

Air Intake Manifold and Aftercooler Cover

The air intake manifold and aftercooler covers were modified for *revision 1* of the aftercooler core. No changes have been made to these components for *revision 2* of the aftercooler core. The revised intake manifold and cover will **not** accept the original aftercooler core. The original manifold and cover will **not** accept either of the revised aftercooler core without rework/machining. The rework/machining procedure is given below. If a revised cover is fitted to an old intake manifold then a new longer roll pin, Part Number 4086080, is required to align the cover.

Parts Information						
Description	Original Part Number	Service Parts Available	Revision 1 Part Number	Service Parts Available	Revision 2 Part Number	Service Parts Available
Air intake manifold	4017703	No	4080571	Yes	4080571	Yes
Air intake manifold	4017704	No	4080572	Yes	4080572	Yes
Aftercooler cover	4001329	No	4080569	Yes	4080569	Yes
Aftercooler cover	4001330	No	4080570	Yes	4080570	Yes
Aftercooler cover gasket	4000713	Yes	4080573	Yes	4080573	Yes
Aftercooler core	4001326	No	4080568	No	4100636	Yes
Roll pin	N/A	N/A	4086080	Yes	4086080	Yes
Clamping plate	N/A	N/A	4066244	Yes	4066244	Yes

Descripti on	Original Aftercoo ler Core, Part Number 4001326	Revision 1 Aftercoo ler Core, Part Number 4080568	Revision 2 Aftercoo ler Core, Part Number 4100636	Original Air Intake Manifold	Air Intake Manifold Revision 1 & 2	Original Aftercoo ler Cover	Aftercoo ler Cover Revision 1 & 2
Original aftercool er core, Part Number 4001326				Y	N	Y	N
Revision 1 aftercool er core, Part Number 4080568				M	Y	M	Y
Revision 2 aftercool er core, Part Number 4100636				M	Y	M	Y
Original air intake manifold	Y	M	M			Y	D
New air intake manifold	N	Y	Y			N	Y
Original aftercool er cover	Y	M	M	Y	N		
New aftercool er cover	Y	Y	Y	D	Y		
Clampin g plate	Y	N	N	Y	N	Y	Y

Chart Key

Y = Yes, will fit with no modifications required

N = No, will **not** fit

M = Will fit after modification, see machine procedure for details of the modification

D = Longer dowel pins are required to align the aftercooler cover and the air intake manifold.

Note : This is a product improvement and is not subject to campaign.

Related Procedures

56-010-008 (/qs3/pubsys2/xml/en/procedures/56/56-010-008.html)	Aftercooler Element (/qs3/pubsys2/xml/en/procedures/56/56-010-008.html)
---	--

Last Modified: 19-Mar-2004
