



# Technical Service Bulletin

Technical Service Bulletin: tsb103848

Released Date: 10-Jun-2009

New IMO Fuel Pump and Kits

## New IMO Fuel Pump and Kits

### Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

**Note : This is a product improvement and is not subject to campaign or temporary repair practice (TRP).**

This Service/Parts Topic describes an issue with the 2004 release of the IMO fuel pump for the following engines:

- QSK23 Industrial and Power Gen
- QSK45 Industrial and Power Gen
- QSK60 Industrial, Power Gen, and Marine
- QSK78 Industrial and Power Gen.

When the new fuel pump was released the old part numbers for the pumps were **not** correctly obsoleted. This Service/Parts Topic informs the field that the old part numbers are obsolete and should no longer be ordered.

The new IMO fuel pump that was released has a design change that places the weep hole in a different location. The location is dependant on both the type of engine and the application. Reference Table 1 for more information:

**Table 1, Part Number Changes**

| Part Name          | Old Part Number | New Part Number | Engine Family |
|--------------------|-----------------|-----------------|---------------|
| Pump, Fuel         | 4062157         | 4903531         | QSK23         |
| Pump, Fuel         | 4062157         | 4603530         | QSK45         |
| Pump, Fuel         | 4062156         | 4903532         | QSK60         |
| Pump, Fuel         | 4062155         | 4903533         | Not Used      |
| Pump, Fuel         | 4061675         | 4903534         | QSK78         |
| Kit, Housing Parts | 4087914         | 4903561         | QSK23         |
| Kit, Housing Parts | 4087914         | 4903562         | QSK45         |
| Kit, Housing Parts | 4076762         | 4903563         | QSK60         |

| Table 1, Part Number Changes |                 |                 |                         |
|------------------------------|-----------------|-----------------|-------------------------|
| Part Name                    | Old Part Number | New Part Number | Engine Family           |
| Kit, Housing Parts           | 4076761         | 4903564         | Not Used                |
| Kit, Housing Parts           | 4076760         | 4903565         | QSK78                   |
| Kit, Housing Parts           | 4087971         | 4903566         | QSK23                   |
| Kit, Front Cover Parts       | 4087971         | 4903567         | QSK45, QSK60, and QSK78 |

The weep hole relocation eliminates the low levels of external weep hole leakage by increasing the weep hole reservoir volume and increasing the evaporation rate by facing the weep hole toward the block. The weep hole moves from the 6 o'clock to the 9 o'clock position on the bottom of the fuel pump.

Related Procedures

|                                                                                             |                                                                                             |
|---------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------|
| <a href="/qs3/pubsys2/xml/en/procedures//.html">(/qs3/pubsys2/xml/en/procedures//.html)</a> | <a href="/qs3/pubsys2/xml/en/procedures//.html">(/qs3/pubsys2/xml/en/procedures//.html)</a> |
|---------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------|