



Technical Service Bulletin

Technical Service Bulletin: TSB110295

Released Date: 07-Nov-2011

Updated High Pressure Injection (HPI) Fuel System Peak Cylinder Pressure Reduction Calibration

Updated High Pressure Injection (HPI) Fuel System Peak Cylinder Pressure Reduction Calibration

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document announces the release of new HPI calibrations for QSK45/60/78 construction engines to aid in the control of excessive Peak Cylinder Pressure (PCP) under specific circumstances.

The following changes have been applied to the calibrations:

1. Injection timing has a varying limit when the intake manifold temperature is below 4.4°C (40°F)
2. Improvements have been made to detect a mismatch between commanded and actual timing fuel pressure. A fault code will now trigger, Fault Code 112.
3. Wetstack table has been changed to improve engine white smoke and stability at light load and low intake manifold temperatures (QSK78 **only**).

The durability of the power cylinder components may be reduced by high PCP. This document informs of the need to update the affected ECMs with these new HPI calibrations.

All construction HPI calibrations for QSK45/60/78 engines have been updated.

ESN Firsts:

- QSK45: 33189032
- QSK60: 33189295
- QSK78: 66301938.

Document History

Date	Details
2011-10-26	Module Created

Date	Details
2011-11-7	QSOL Quick Fix Reason: Outfile Notes: none

Last Modified: 07-Nov-2011
