



Technical Service Bulletin

Technical Service Bulletin: TSB120020

Released Date: 09-Apr-2012

QSK19, QSK45, and QSK60 Increase in Torque for Injector Rocker Lever Adjusting Screw Locknut

QSK19, QSK45, and QSK60 Increase in Torque for Injector Rocker Lever Adjusting Screw Locknut

Core Issue

Injector rocker lever adjusting screw locknuts have come loose over time. This can increase the lash and then lead to a "no follow" condition.

Confirmation

Inspect the injector rocker lever adjusting screw locknuts to see if any are loose.

Resolution

There has been an increase in the torque specified for the QSK19, QSK45, and QSK60 rocker lever adjusting screw locknut from 50 N•m [37 ft-lb] to 105 N•m [77 ft-lb].

The new torque value was in production with engine serial number (ESN) first 33183244 (build date 27th October, 2010) for QSK45/60 engines and 37253009 (build date 26th January, 2012) for QSK19 engines. The service manuals have also been updated to reflect this change.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Document History

Date	Details
2012-1-17	Module Created
2012-4-4	update to include QSK19 engines

Last Modified: 09-Apr-2012

