



Technical Service Bulletin

Technical Service Bulletin: TSB140160

Released Date: 14-Nov-2014

New QSK60 Turbocharger Kit

New QSK60 Turbocharger Kit

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document announces the release of a new turbocharger and turbocharger kit.

Product Affected

QSK60 engines.

Description of Change

A c-seal joint has been added to the turbocharger.

Reason for Change

Address breakage of A286 stainless steel capscrews. The capscrews are used to mount the turbocharger bearing housing to the turbocharger turbine housing on HE800FG turbochargers.

Service Part Available

A complete turbocharger kit is available. See Tables 1 and 2 for part numbers. This turbocharger kit should be used in place of the short-term solution which was shim kit, Part Number 4034095.

Table 1, Turbocharger Kit Information

Part Number	Part Description	Quantity
5321612	Kit, Turbocharger	1

Table 2, Turbocharger Kit Contents

Part Number	Part Description	Quantity
3793677	Turbocharger, Aftermarket	1
4032567	Kit, Turbocharger Gasket	1

Part Structure

The existing turbocharger and turbocharger kit part numbers have been obsoleted and superseded by the new part numbers. The parts are backward compatible and transparent to assembly.

Part Disposition

Use existing turbocharger kit inventory before using the new part number.

Production Status

Implemented for production, however, ESN first and build date information is **not** available.

Publications Affected

None.

Document History

Date	Details
2014-11-11	Module Created

Last Modified: 14-Nov-2014
