



Technical Service Bulletin

Technical Service Bulletin: TSB200112

Released Date: 01-Jun-2020

QSK60 CM500 Lube Pump White Stripe Check

QSK60 CM500 Lube Pump White Stripe Check

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

QSK60 CM500

Issue

Symptom: Engine shows red lamp in cab and speed derate. Cummins technician confirms through ECM fault code FC415 Low Oil Pressure.

Root Cause: Gear bolts have not been torqued correctly from the supplier meaning there is less pre-load.

- The cap screws start to back out and cause fretting on the mating surfaces.
- At least two of the bolts back out leaving the final bolt to maintain the gear loading.
- All of the bolts fracture losing oil pressure.

Verification/Confirmation

Multiple returned lube pumps have been analyzed in the Cummins Metallurgy labs with the same failure mechanism as above being identified.

Resolution

Check the bolts and gear for the white stripe as shown below.



Figure 1, Bolts and Gears

If the white stripes are present, no further action is required and the lube pump can be installed to the engine.

If there are no white stripes, follow the torque instructions for the bolts in manual 4021530, Section 007, Procedure 031.

Reason for Change

The supplier has started applying the while stripe to confirm they have completed the torque overchecks. We require all customers to check for this stripe to prevent lube pumps with insufficient torque being fitted to engines.

Part Compatibility

Fully compatible.

Document History

Date	Details
2020-5-12	Module Created

Last Modified: 01-Jun-2020