



Technical Service Bulletin

Technical Service Bulletin: TSB200225

Released Date: 20-Nov-2020

Lifting Eye and Rocker Bolt Capscrew

Lifting Eye and Rocker Bolt Capscrew

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK60 CM500
- QSK60 CM850
- QSK60 CM2150
- QSK60 CM2350 K116
- QSK60 CM2350 K117
- QSK60 CM2350 K121
- QSK60 CM2350 K135
- QSK60 CM2350 K136

Issue

The supplier was changed for the lifting eye and rocker levers. During this change the flange thickness was changed from 5 mm to 2.4 mm. This has led to the flange yielding during torquing. The bolts, 3089194 and 3089193, should only be used if they have the 5 mm flange. The 2.4 mm flange **must** be quarantined and direction followed for the parts alert mentioned below.

Verification/Confirmation

The good bolts can be seen visually as shown below or they can be measured using suitable measuring equipment.



Figure 1, Good and Bad Bolt

Resolution

Bolts with the correct flange size have been received in Daventry. They are currently being sent to the distribution facilities Following the parts alert all, further parts received should be of the 5 mm flange.

Service Parts Availability

Service parts are available.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Rocker Lever Cap-Screw	3089193	N/A	N/A	N/A
Lifting Eye Cap-Screw	3089194	N/A	N/A	N/A

Part Compatibility

Fully compatible.

Part Identification

The parts can be identified visually as shown in the image above or with suitable measuring equipment.

Part Inventory Action

In stock parts are affected. See Parts Alert 2020-033 for details.

Document History

Date	Details
2020-11-19	Module Created