



Technical Service Bulletin

Technical Service Bulletin: TSB210250

Released Date: 11-Jan-2022

New Lubricating Oil Pan Adapter

New Lubricating Oil Pan Adapter

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK60 CM2150 K132M
- QSK60 CM2150 MCRS
- QSK60 CM2250
- QSK60 CM2250 K112
- QSK60 CM2350 K116
- QSK60 CM2350 K117
- QSK60 CM2350 K121
- QSK60 CM2350 K133
- QSK60 CM2350 K135
- QSK60 CM2350 K136
- QSK60 CM2350 K149M
- QSK60 CM500
- QSK60 CM850 MCRS

Description of Change

The corner radius has been increased from 13 mm to 16 mm.

Reason for Change

- There have been numerous reports of lubricating oil pan adapters cracking. Once analyzed, the initiation point has been identified as the corner of the lubricating oil pan. This latest lubricating oil pan changes the radius at this location from 13 mm to 16 mm allowing better control during manufacture.
- The original design during manufacture created a drop in wall thickness at the fracture location reducing lubricating oil pan adapter strength. This increased radius prevents a loss of wall thickness in this location.

Service Parts Availability

Service parts are available. See Table 1 below for part numbers.

Table 1, Service Parts				
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Oil Pan Adapter	3636014	Yes	Yes	5541962
Oil Pan Adapter	3636015	Yes	Yes	5541963
Oil Pan Adapter	3636016	Yes	Yes	5541964
Oil Pan Adapter	4924772	Yes	Yes	5541965
Oil Pan Assembly	3637962	Yes	Yes	5541966
Oil Pan Assembly	3636522	Yes	Yes	5541970
Oil Pan Assembly	3636525	Yes	Yes	5541971
Oil Pan Assembly	3636526	Yes	Yes	5541972
Pre Lube Bracket	5538078/ 4372836	Yes	Yes	5542166
Pre Lube Bracket	5538083/4372837	Yes	Yes	5542170

Part Compatibility

- If moving from existing lubricating oil pan adapter to the new lubricating oil pan adapter for for QSK60 CM2150 Genset applications, a new pre-lube pump bracket **must** also be purchased. See Table above 1 for part numbers.
- New parts are compatible with all QSK60 Engines if a new pre-lube bracket is purchased.

Part Inventory Action

Use existing part number inventory before using the new part number.

Production Status

Implemented for production. See Table 2 below.

Table 2, Production Information			
Adapter Part Number	ESN First	Build Date ¹	Plant
5541976	33225532	19 July 2021	Daventry
5541982	33225567	21 July 2021	Daventry
5541978	33225646	29 July 2021	Daventry
5541980	33225627	27 July 2021	Daventry
5541989	33225610	26 July 2021	Daventry
5541988	33225692	3 August 2021	Daventry
5541967	33225855	18 August 2021	Daventry
5541966	33226022	3 September 2021	Daventry

Table 2, Production Information			
Adapter Part Number	ESN First	Build Date ¹	Plant
5541975	33225530	20 July 2021	Daventry
5541984	33225528	19 July 2021	Daventry
5541981	33225611	26 July 2021	Daventry

Document History

Date	Details
2021-11-5	Module Created
2021-11-12	Added for QSK60 CM2150 Genset applications statement in Part Compatibility section.
2022-1-11	Updated Table 1.

Last Modified: 11-Jan-2022
