



Technical Service Bulletin

Technical Service Bulletin: TSB240108

Released Date: 20-Apr-2026

New Prelube Solenoid

New Prelube Solenoid

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK60 CM500
- QSK60 CM2250 K112
- QSK60 CM2150 MCRS
- QSK60 CM850 MCRS
- QSK60 CM2150 MCRS G
- QSK60 CM2350 K116
- QSK60 CM2350 K117
- QSK60 CM2350 K136
- QSK60 CM2350 K121
- QSK60 CM2350 K135
- QSK78 CM500
- QSK78 CM2350 K126
- QSK78 CM2350 K137
- QSK78 CM2350 K154C

Description of Change

This document announces a new prelube solenoid, which requires related new OEM mounting bracketry and associated parts. The new bracketry ensures the correct orientation of the solenoid and offers the mounting arrangement required by the new prelube solenoid because of a change in the mounting dimensions.

Reason for Change

A malfunction rate of the prelube solenoid has existed on multiple machines, stemming from vibration resulting in internal mechanical malfunction. To improve reliability, a new prelube solenoid and associated bracketry have been released to mitigate vibration and the resulting malfunction mechanism.

Service Parts

- New OEM mounting bracketry and associated parts are the responsibility of the OEM. See equipment manufacturer service information.
- The new mounting bracketry and associated parts **must** be used when fitting the new prelube solenoid part number. See Table 1 for part number information.

Service parts are offered. See Table 1 for part numbers.

Table 1, Service Parts				
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Prelube Solenoid	4951864	No	No	5578249

Part Compatibility

New OEM mounting bracketry and associated parts **must** be used when fitting the new prelube solenoid. See Table 1 for part number information.

Part Inventory Action

- QSK78 Products Affected: Use new prelube solenoid part number at point of TSB release.
- QSK60 Products Affected: The new prelube solenoid part number is **not** used in production units. Use the new prelube solenoid part number as an approved countermeasure if the existing prelube solenoid part number has a high malfunction rate.
- All Other Products: Continue to use existing prelube solenoid part number.

Document History

Date	Details
2024-5-14	Module Created
2026-2-4	Added QSK60 to the Product Affected list. Added QSK60 to Part Inventory Action.
2026-4-20	Amended QSK60 note in the Part Inventory Action