



Technical Service Bulletin

Technical Service Bulletin: TSB101102

Released Date: 24-Feb-2011

Improved Cylinder Head Capscrew Coating

Improved Cylinder Head Capscrew Coating

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document introduces a new cylinder head capscrew for QSK45 and QSK60 series engines.

The new cylinder head capscrews, Part Number 3644387, obsoletes and supersedes the old capscrew, Part Number 4080253. The new capscrew has an improved coating for better resistance. The new capscrew can be mixed with the old capscrew on the same cylinder head, with no adverse effects on engine performance.

The new coating does **not** affect the torque sequence or value. However, Procedure 002-004 has been updated to include new inspect for reuse guidelines for these capscrews. The capscrews can be cleaned with typical cleaning solvent, but **must not** be cleaned with a wire brush, as this can damage the coating.

The ESN first for the change is 33185146.

Description	Old Part Number	New Part Number
Screw, Fracture Resistant	4080253	3644387

Document History

Date	Details
2010-11-23	Module Created
2011-2-24	QSOL Quick Fix Reason: Spelling Error Notes: none

Last Modified: 24-Feb-2011