



Technical Service Bulletin

Technical Service Bulletin: TSB140091

Released Date: 05-Feb-2018

New QSK45 and QSK60 Low Temperature Aftercooler (LTA) Water Pump

New QSK45 and QSK60 Low Temperature Aftercooler (LTA) Water Pump

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document announces the release of a new low temperature aftercooler (LTA) water pump. The new pump has several improvements. A revised bearing system is installed, where the rear bearing has been changed from a ball bearing to a roller bearing. The new pump also has an improved duckbill filter in one of the weep holes to stop dirt and debris from entering the weep chambers. The secondary weep hole will also be closed off with a plug. There is also a revision to the banjo bolt, which is used to control oil flow to the pump bearings. The new banjo bolt has a smaller restriction to provide the correct oil flow to the bearings. The new part numbers can be found in the table below.

Note : The Komatsu HD1500 application now no longer has a unique part.

The engine serial number (ESN) first in production for this Pump is 33201208.

Low Temperature Aftercooler (LTA) Water Pump Part Numbers

Part Description	Existing Part Number	New Part Number
LTA Pump Kit (Cquantity o tains all parts and 1-pump)	4955807	4376080
Banjo Bolt	3638094	4372963
Tube Connector	-	3252438
Water Drain Tube (Duckbill Filter)	-	3650016
Flexible Hose	-	3642576
Male Union Elbow	-	3682701
Seal Washers (Quantity 2)	-	3963982
Clip	-	68152

Document History

Date	Details
2014-7-1	Module Created
2018-1-8	Updated parts table.

Last Modified: 05-Feb-2018
