



Technical Service Bulletin: TSB160012

Released Date: 11-May-2016

New High Pressure Turbocharger Turbine Housing and Service Kit

New High Pressure Turbocharger Turbine Housing and Service Kit

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK60 CM850 MCRS
- QSK60 CM2150 MCRS

Issue

Select engines with a horsepower rating of 2850 hp and Fuel Rating option FR 6773, have experienced high pressure turbocharger mounting flange cracking. The high pressure turbocharger mounting flange crack can create an exhaust gas leak.

Verification

A visual inspection of the high pressure turbocharger to exhaust manifold mounting flange can determine if the high pressure turbocharger mounting flange has cracked.

Resolution

The high pressure turbocharger turbine housing should be replaced if found to have a crack at the mounting flange. A new high pressure turbocharger turbine housing service kit has been released to enable the replacement of a high pressure turbocharger turbine housing which has suffered a cracked mounting flange. The new high pressure turbocharger turbine housing has a redesigned mounting flange.

Service Instructions

For high pressure turbocharger turbine housing replacement information, see QSK45 and QSK60 Service Manual, Bulletin 4021530. Refer to Procedure 010-033 (</qs3/pubsys2/xml/en/procedures/56/56-010-033-tr.html>) in Section 10.

Service Parts Availability

Table 1, High Pressure Turbocharger Turbine Housing Service Kit, Part Number 4034348, Contents	
Part Description	New Part Number
Kit, Turbocharger Gasket	3786265
Kit, Turbocharger Repair	4032182
Housing, Turbine	5330001

Document History

Date	Details
2016-2-5	Module Created
2016-2-24	Corrected title.
2016-5-9	Changed part number 4376271 to 3786265.

Last Modified: 11-May-2016
